


INFORMATION DISCLOSURE
CITATION

(Use several sheets if necessary)



Atty. Docket N . 2018-852 Serial No. 10/790,779
Applicant WAKAHARA et al
Filing Date March 3, 2004 TC/A.U. 2855

U.S. PATENT DOCUMENTS

| *EXAMINER INITIAL | DOCUMENT NUMBER | DATE | NAME | CLASS | SUBCLASS | FILING DATE IF APPROPRIATE |
|-------------------|-----------------|------|------|-------|----------|----------------------------|
| | | | | | | |

FOREIGN PATENT DOCUMENTS

TRANSLATION

| DOCUMENT | DATE | COUNTRY | CLASS | SUBCLASS | YES | NO |
|----------|------|---------|-------|----------|-----|----|
| | | | | | | |

OTHER DOCUMENTS (including Author, Title, Date, Pertinent pages, etc.)

| | |
|------------|--|
| <u>LLA</u> | 1997 Chevrolet Malibu, Oldsmobile Cutlass Service Manual; GMP/97-LN-2; Book 2; L/N Platform; 08/1996; pp 6E-94, 6E-95 |
| <u>LLA</u> | 1998 Malibu and Cutlass Service Manual; GMP/09LN-3; L/N Platform; Volume 3; 06/1997; pp 6-562, 6-563, 6-994-995 |
| <u>LLA</u> | 1996 Cadillac DeVille/Concours/Eldorado/Seville Service Information; Book 2 Powertrain; E/K Platform; 1996; 6E-96-97 |
| <u>LLA</u> | 1996 Cadillac DeVille/Concours/Eldorado/Seville New Product Service Information; 1995; 6E-A-121-122 |
| <u>LLA</u> | 1998 DeVille and Eldorado Service Manual; Volume 3; 7/1997; 6-378-379 |
| <u>LLA</u> | 1997 DeVille/Eldorado/Seville Service Manual; GMP/97-EK-2; Book 2; 3/1997; 6-338-339 |
| <u>LLA</u> | 1996 Cadillac Fleetwood (Rear Wheel Drive) Service Information; Book 2 Powertrain; D Platform; 4/1996; 6E-A-87-89; |
| <u>LLA</u> | 1996 Cadillac Fleetwood New Product Service Information; 1995; 6E3-A-86-88 |
| <u>LLA</u> | 1996 Chevrolet Lumina, Monte Carlo, Pontiac Grand Prix, Oldsmobile Cutlass Supreme and Buick Regal Service Manual; GMP/96-W-2P; Book 2 (Preliminary); W Platform; 06/1995; 6E3-A-84-85 |
| <u>LLA</u> | 1996 Chevrolet Lumina, Monte Carlo, Pontiac Grand Prix, Oldsmobile Cutlass Supreme and Buick Regal Service Manual; GMP/96-W-2; Book 2; W Platform; 4/1996; 6E-A-872-874 |
| <u>LLA</u> | 1997 Pontiac Grand Prix Service Manual; Book 2; W Platform; 9/1996; 6E-95-96; 6E-521-522 |
| <u>LLA</u> | 1997 Buick Century and Regal Service Manual; Book 3; W Platform; 1/1997; 6E-100-101; 6E-570-571 |
| <u>LLA</u> | 1998 Pontiac Grand Prix Service Manual; GMP/98-WP-3; Volume 3; W Platform; 5/1997; 6-696-697; 6-1276-1277 |
| <u>LLA</u> | 1996 Chevrolet Corsica/Beretta Service Manual; GMP/96-L-2P; Book 2 (Preliminary); L Platform; 6/1995; 6E3-A-76-77; 6E3-A-85 |
| <u>LLA</u> | 1996 Chevrolet Corsica/Beretta Service Manual; GMP/96-L-2; Book 2; L Platform; 2/1996; 6E-432-433 |
| <u>LLA</u> | 1996 Chevrolet Lumina, Pontiac Trans Sport, Oldsmobile Silhouette Service Manual; GMP/96-U-2P; Book 2 (Preliminary); U-Van Platform; 9/1995; 6E3-A-93-94 |
| <u>LLA</u> | 1996 Chevrolet Lumina, Pontiac Trans Sport, Oldsmobile Silhouette Service Manual; GMP/96-U-2; Book 2; U-Van Platform; 3/1996; 6E-96-97 |
| <u>LLA</u> | 1997 Chevrolet Venture, Pontiac Trans Sport, and Oldsmobile Silhouette Service Manual; GMP/97-U-2; Book 2; U-Platform; 10/1996; 6E-99-100 |
| <u>LLA</u> | 1998 Chevrolet Venture, Pontiac Trans Sport and Oldsmobile Silhouette Service Manual; GMP/98-U-3; Volume 3; U-Platform; 6/1997; 6-456-457 |
| <u>LLA</u> | 1997 Pontiac Grand Am, Oldsmobile Achieva and Buick Skylark Service Manual; GMP/97-N-2; Book 2; N-Platform; 05/1996; 6E-93-94; 6E-486-487 |
| <u>LLA</u> | 1998 Grand Am, Achieva and Skylark Service Manual; GMP/98-N-3; Volume 3; N Platform; 05/1997; 6-565-566; 6-974 |
| <u>LLA</u> | 1996 Park Avenue, LeSabre, Ninety-Eight, Eighty-Eight and Bonneville Service Manual; GMP/96-CH-2P; Book 2 (Preliminary); C/H Platform; 06/1995; 6E3-A-112-113 |
| <u>LLA</u> | 1996 Park Avenue, LeSabre, Ninety-Eight, Eighty-Eight and Bonneville Service Manual; GMP/96-CH-2; Book 2; C/H Platform; 03/1996; 6E-114-115 |
| <u>LLA</u> | 1997 LeSabre, Eighty-Eight and Bonneville Service Manual; GMP/97-H-2; Book 2; H Platform; 5/1996; 6E-118-119 |

*Examiner

J. M. M.

Date Considered

JAN. 10, 2005

Examiner: Initial if reference considered, whether or not citation is in conformance with MPEP 609; Draw line through citation if not in conformance and not considered. Include copy of this form with next communication to application.

| | | |
|------------------------------------|------------------|------------|
| INFORMATION DISCLOSURE CITATION | ATTY. DOCKET NO. | SERIAL NO. |
| | 2018-852 | 10/790,779 |
| | APPLICANT | |
| (Use several sheets if necessary) | WAKAHARA et al | |
| | FILING DATE | GROUP |
| | March 3, 2004 | 2855 |





U.S. PATENT DOCUMENTS

FOREIGN PATENT DOCUMENTS

OTHER DOCUMENTS (including Author, Title, Date, Pertinent pages, etc.)

| | |
|-----------|--|
| <i>AM</i> | Document ID#65878; 1997 GMC Truck Yukon-4WD; DTC P0125 Engine Coolant Temperature (ECT) Insufficient for Closed Loop Fuel Control; 4 pages |
| <i>LM</i> | Document ID#13253; 1996 GMC Sonoma; DTC P0125 Engine Coolant Temperature (ECT) Insufficient For Closed Loop Fuel Control; 4 Pages |
| | |
| | |
| | |

***Examiner**

Date Considered

Jan. 10, 2005

Examiner: Initial if reference considered, whether or not citation is in conformance with MPEP 609; Draw line through citation if not in conformance and not considered. Include copy of this form with next communication to application.

Form PTO-FB-AB20 (Also PTO-1449)

**INFORMATION DISCLOSURE
CITATION**

(Use several sheets if necessary)

| | |
|-----------------------|-------------------|
| Atty. Docket No. | Serial No. |
| 2018-852 | 10/790,779 |
| Applicant | |
| WAKAHARA et al | |
| Filing Date | TC/A.U. |
| March 3, 2004 | 2855 |

| | |
|---------------|--|
| HA | 1998 LeSabre, Eighty-Eight and Bonneville Service Manual; GMP/98-H-3; Volume 3; H Platform; 5/1997; 6-409-410 |
| HA | 1996 Chevrolet Cavalier and Pontiac Sunfire Service Manual; GMP/96-J-2P; Book 2 (Preliminary); J Platform; 5/1995; 6E3-A-78-79; 6E3-A-85-87 |
| HA | 1996 Chevrolet Cavalier and Pontiac Sunfire Service Manual; GMP/96-J-2; Book 2; J Platform; 2/1996; 6E-92-93; 6E-476-477 |
| HA | 1997 Chevrolet Cavalier and Pontiac Sunfire Service Manual; GMP/97-J-2; Book 2; J Platform; 5/1996; 6E-95-96; 6E-502-503 |
| HA | 1995 Chevrolet Camaro and Pontiac Firebird Service Manual Supplement; GMP/95-F-UPD; F Platform; 12/1994; 6E3-A-97; 6E3-A-100 |
| HA | 1996 Chevrolet Camaro and Pontiac Firebird Service Manual; GMP/96-F-2P; Book 2 (Preliminary); F Platform; 6/1995; 6E3-A-96-97; 6E3-A-90-91 |
| HA | 1996 Chevrolet Camaro and Pontiac Firebird Service Manual; GMP/96-F-2; Book 2; F Platform; 3/1996; 6E-103; 6E-547-548 |
| HA | 1997 Chevrolet Camaro and Pontiac Firebird Service Manual; GMP/97-F-2; Book 2; F Platform; 5/1996; 6E-102-103; 6E-566-567 |
| HA | 1998 Chevrolet Camaro and Pontiac Firebird Service Manual; GMP/98-F-3; Volume 3; F Platform; 6/1997; 6-706-707; 6-1280-1281 |
| HA | 1996 Chevrolet Corvette Service Manual; Book 2; Y Platform; 1/1996; 6-366-367 |
| HA | 1997 Corvette Service Manual; GMP/97-Y-3; Book 3; Y Platform; 3/1997; 6-483-484 |
| HA | 1998 Corvette Preliminary Service Manual; Volume 3; Y Platform; 4/1997; 6-480-481 |
| HA | 2000 Service Manual - Pontiac; GMP/00-HP-1; H Platform; Volume 1; 6-418; 6-213 |
| HA | 2000 Service Manual - Buick Le Sabre; 6-357; 6-174 |
| HA | 2000 Service Manual - Chevrolet Cavalier and Pontiac Sunfire; GMP/00-J-1; J-Platform; Volume 1; 6-571; 6-379-380 |
| HA | 2000 Service Manual - Pontiac Grand Am and Oldsmobile Alero; M-Platform; 6-594; 6-426-427 |
| HA | 2001 Service Manual - Chevrolet Cavalier and Pontiac Sunfire; GMP/01-J-1; J-Platform; Volume 1; 6-575; 6-415 |
| HA | 2001 Service Manual - Chevrolet Venture, Pontiac Montana and Oldsmobile Silhouette; GMP/01-U-1; U-Platform; Volume 1; 6-420; 6-250 |
| HA | 2001 Service Manual - Chevrolet Silverado, Suburban, Tahoe and GMC Sierra, Yukon, Yukon XL, Denali, Denali XL; CK8 Truck; GMP/01-CK8-2; Volume 2; 6-2863; 6-1437 |
| HA | 2001 Service Manual - Chevrolet Impala, Monte Carlo; GMP/01-WCI-2; W-Platform; Volume 2; 6-1127; 6-517 |
| HA | 2001 Service Manual - Chevrolet Malibu; L/N-Platform; 6-355; 6-219 |
| HA | 2002 Service Manual - Buick Le Sabre; 6-429; 6-263 |
| HA | 2003 Service Manual - Cadillac CTS; GMP/03-D-1; Volume 1; 6-579; 6-336 |
| HA | 2003 Service Manual - Cadillac Seville; GMP/03-K-1; 6-719; 6-508 |
| HA | 2003 Service Manual - Chevrolet Impala, Monte Carlo; GMP/03-WCI-2; Volume 2; 6-1113; 6-467 |
| HA | 2003 Service Manual - Chevrolet Tahoe, Suburban, Avalanche, GMC Yukon/Yukon XL, Yukon Denali/Yukon XL Denali, Cadillac Escalade/Escalade ESV, Escalade EXT; GMP/03-CKUV-2; Volume 2; 6-1412; 6-619 |
| HA | 2004 Service Manual - Chevrolet Tahoe, Suburban, Avalanche, GMC Yukon/Yukon XL, Yukon Denali/Yukon XL Denali, Cadillac Escalade/Escalade ESV, Escalade EXT; CK8 Truck; 6-897; 6-1464; 6-621 |
| HA | 2004 Service Manual - Buick Rainier, Chevrolet TrailBlazer, GMC Envoy; GMP/04-STNS-2; ST Truck; Volume 2; 6-826; 6-1243; 6-622 |

| | | | |
|-----------|--------------------|-----------------|----------------------|
| *Examiner | <i>LL. M. Hall</i> | Date Considered | <i>JAN. 10, 2005</i> |
|-----------|--------------------|-----------------|----------------------|

Examiner: Initial if reference considered, whether or not citation is in conformance with MPEP 609; Draw line through citation if not in conformance and not considered. Include copy of this form with next communication to application.

| | | | |
|--|--|-----------------------------|--------------|
| INFORMATION DISCLOSURE CITATION | | ATTY. DOCKET NO. | SERIAL NO. |
| | | 2018-852 | 10/790,779 |
| | | APPLICANT | |
| DEC 01 2004 (Use several sheets if necessary) | | WAKAHARA et al (as Amended) | |
| | | FILING DATE | GROUP |
| | | March 3, 2004 | unknown 2855 |

U.S. PATENT DOCUMENTS

FOREIGN PATENT DOCUMENTS

OTHER DOCUMENTS (including Author, Title, Date, Pertinent pages, etc.)

| | |
|-----|--|
| 111 | WAKAHARA et al; U.S. Application No. 10/986,228 filed November 12, 2004; "THERMOSTAT MALFUNCTION DETECTING SYSTEM FOR ENGINE COOLING SYSTEM"; Claims 37-78 (only) |
| 111 | WAKAHARA et al; U.S. Application No. 10/984,931 filed November 10, 2004; "THERMOSTAT MALFUNCTION DETECTING SYSTEM FOR ENGINE COOLING SYSTEM"; Claims 37-49 (only) |
| 111 | WAKAHARA et al; U.S. Application No. 10/984,980 filed November 10, 2004; "THERMOSTAT MALFUNCTION DETECTING SYSTEM FOR ENGINE COOLING SYSTEM"; Claims 37-119 (only) |

*Examiner

1. ~~111~~

Date Considered

Jan. 16, 2005

Examiner: Initial if reference considered, whether or not citation is in conformance with MPEP 609; Draw line through citation if not in conformance and not considered. Include copy of this form with next communication to application.

Form PTO-FB-A820 (Also PTO-1449)